


WIRING DIAGRAM



- A. Water inlet valve
- B. Water pump
- C. Compressor
- D. Compressor start relay
- E. Thermal overload
- F. Fan motor
- G. 10 amp, 3 pin plug
- H. Terminal block
- I. Timer
- J. Bin thermostat
- K. Evaporator thermostat
- L. Fan control

- BL Blue
- B Black
- G Green
- R Red
- W White
- BR Brown
- YG Yellow/Green